

1/9

FIGURE 1




Fig. 1

FIGURE 3






FIGURE 2



3/9

FIGURE 4



4/9

FIGURE 5




Fig. 5

5/9

FIGURE 6





FIGURE 7



A schematic diagram of a mechanical assembly. It features a vertical shaft-like component on the left, a curved arm extending from it, and a base with diagonal hatching. Various parts are labeled with numbers: 3 points to the top of the shaft; 4, 7, 8, and 10 point to a joint or connection area; 5 points to the curved arm; 6 points to a horizontal force arrow at the joint; 9 points to the hatched base area; and 10 points to a small rectangular feature near the joint. Arrows indicate forces or movement: a large upward arrow on the right, a horizontal arrow pointing left at the bottom right, and several arrows at the bottom left.

-Fig. 8




FIGURE 9



9/9




FIGURE 10